

DETERIORATED DWELLING UNITS

-  1 - 2 UNITS
-  3 OR MORE





Figure 8
 GENERALIZED LOCATIONS OF DETERIORATED DWELLING UNITS
 City of Clearwater, Kansas, 2003



● 5 DWELLING UNITS




Figure 9
 DWELLING UNIT DENSITY PATTERNS
 City of Clearwater, Kansas